



### VARI-CRIMP to CS CROSS REFERENCE

324V	CS09-3X4
400V	CS01-4X2
403V	CS01-4X4
406V	CS04-4X4
409V	CS05-4X4
4100V	CS28-4X4
4103V	CS28-4X5
4106V	CS18-4X4
4109V	CS19-4X4
4112V	CS20-4X4
4127V	CS25-4X4
412V	CS02-4X4
4130V	CS26-4X4
4132V	CS24-4X4
4133V	CS18-4X5
4136V	CS19-4X5
4139V	CS20-4X5
4151V	CS68-4X5
4154V	CS25-4X5
4157V	CS26-4X5
415V	CS01-4X6
4160V	CS26-4X6
4163V	CS27-4X4
4166V	CS27-4X5
4169V	CS18-4X3
4172V	CS19-4X3
4175V	CS20-4X3
4178V	CS27-4X6
4181V	CS25-4X6

418V	CS08-4X4
4206V	CS14-4X4
421V	CS08-4X5
4224V	CS17-4X4
424V	CS09-4X4
427V	CS09-4X5
430V	CS08-4X6
433V	CS09-4X6
436V	CS02-4X2
439V	CS01-4X8
442V	CS07-4X6
445V	CS03-4X8
448V	CS11-4X6
445V	CS13-4X4
451V	CS11-4X4
454V	CS11-4X5
457V	CS12-4X4
462V	CS04-4X2
466V	CS04-4X6
481V	CS10-4X4
484V	CS16-4X4
486V	CS10-4X6
4A24V	CS32-4X4
4A26V	CS32-4X6
4A64V	CS33-4X4
4A66V	CS33-4X6
4C06V	CS37-4X6
4C08V	CS37-4X8
4C10V	CS37-4X10

4C58V	CS38-4X8
4C60V	CS38-4X10
4D08V	CS41-4X8
4D10V	CS41-4X10
4D58V	CS44-4X8
4D60V	CS44-4X10
4E64V	CS29-4X4
4H10V	CS42-4X10
4H60V	CS45-4X10
4J34V	CS34-4X4
4J36V	CS34-4X6
4K14V	CS39-4X14
4L04V	CS40-4X4
4L06V	CS40-4X6
4L64V	CS31-4X4
4L66V	CS31-4X6
4M08V	CS66-4X8
4M58V	CS67-4X8
4M60V	CS67-4X10
4P44V	CS43-4X4
4P54V	CS36-4X4
4P74V	CS46-4X4
4S64V	CS30-4X4
4S66V	CS30-4X6
4S68V	CS30-4X8
4T04V	CS21-4X4
4T54V	CS35-4X4
600V	CS01-6X4
603V	CS01-6X6

603VLN	CS01-6X6LN
606V	CS05-6X6
609V	CS04-6X6
6103V	CS28-6X5
6106V	CS28-6X6
6109V	CS18-6X5
6112V	CS19-6X5
6115V	CS20-6X5
6124V	CS27-6X8
612V	CS02-6X6
6130V	CS25-6X5
6133V	CS26-6X5
6136V	CS18-6X6
6139V	CS19-6X6
6142V	CS20-6X6
6148V	CS22-6X6
6151V	CS23-6X6
6157V	CS25-6X6
615V	CS01-6X8
6160V	CS26-6X6
6162V	CS24-6X6
6163V	CS26-6X8
6166V	CS27-6X6
6169V	CS25-6X8
6172V	CS23-6X6L
6175V	CS18-6X4
6178V	CS19-6X4
6181V	CS20-6X4
6184V	CS25-6X4



### VARI-CRIMP to CS CROSS REFERENCE

6187V	CS26-6X4
618V	CS08-6X6
6190V	CS27-6X4
6193V	CS18-6X7
6196V	CS19-6X7
6199V	CS20-6X7
6209V	CS14-6X6
621V	CS08-6X8
6227V	CS17-6X6
6230V	CS17-6X8
6242V	CS15-6X10
6245V	CS15-6X8
624V	CS06-6X6
6251V	CS14-6X8
6278V	CS15-6X6
627V	CS09-6X6
630V	CS09-6X8
633V	CS07-6X6
636V	CS11-6X6
639V	CS11-6X8
642V	CS11-6X10
645V	CS12-6X8
648V	CS05-6X8
651V	CS04-6X8
657V	CS09-6X10
660V	CS03-6X8
663V	CS02-6X4
666V	CS04-6X4
669V	CS08-6X10

66SV	CS13-6X6
675V	CS09-6X4
678V	CS12-6X6
6800V	CS28-6X8
681V	CS10-6X6
684V	CS16-6X6
688V	CS02-6X8
691V	CS09-6X12
694V	CS10-6X8
6A24V	CS32-6X4
6A26V	CS32-6X6
6A28V	CS32-6X8
6A66V	CS33-6X6
6A68V	CS33-6X8
6C10V	CS37-6X10
6C12V	CS37-6X12
6C60V	CS38-6X10
6C62V	CS38-6X12
6C64V	CS38-6X14
6D10V	CS41-6X10
6D12V	CS41-6X12
6D60V	CS44-6X10
6D62V	CS44-6X12
6E66V	CS29-6X6
6E68V	CS29-6X8
6H12V	CS42-6X12
6H62V	CS45-6X12
6H64V	CS45-6X14
6J36V	CS34-6X6

6J38V	CS34-6X8
6K18V	CS39-6X18
6L06V	CS40-6X6
6L66V	CS31-6X6
6L68V	CS31-6X8
6M10V	CS66-6X10
6M12V	CS66-6X12
6M60V	CS67-6X10
6M62V	CS67-6X12
6M64V	CS67-6X14
6P46V	CS43-6X6
6P56V	CS36-6X6
6P58V	CS36-6X8
6P76V	CS46-6X6
6S64V	CS30-6X4
6S66V	CS30-6X6
6S68V	CS30-6X8
6T06V	CS21-6X6
6T56V	CS35-6X6
800V	CS01-8X6
803V	CS01-8X8
806V	CS05-8X8
809V	CS04-8X8
8103V	CS28-8X8
8106V	CS28-8X10
8109V	CS18-8X8
8112V	CS19-8X8
8115V	CS20-8X8
8127V	CS68-8X8

812V	CS02-8X8
8130V	CS25-8X8
8133V	CS26-8X8
8134V	CS24-8X8
8136V	CS18-8X10
8139V	CS19-8X10
8154V	CS68-8X10
8157V	CS25-8X10
815V	CS08-8X8
8160V	CS26-8X10
8163V	CS27-8X8
8166V	CS27-8X10
818V	CS08-8X10
8209V	CS14-8X8
8224V	CS17-8X8
8227V	CS17-8X10
8236V	CS15-8X8
8239V	CS15-8X10
824V	CS09-8X8
827V	CS09-8X10
830V	CS11-8X8
833V	CS11-8X10
836V	CS12-8X8
839V	CS12-8X10
842V	CS09-8X6
845V	CS09-8X12
848V	CS08-8X12
854V	CS01-8X12
857V	CS04-8X6



### VARI-CRIMP to CS CROSS REFERENCE

860V	CS11-8X12
863V	CS09-8X16
866V	CS01-8X4
881V	CS10-8X8
884V	CS16-8X8
885V	CS13-8X8
8A26V	CS32-8X6
8A28V	CS32-8X8
8A30V	CS32-8X10
8A32V	CS32-8X12
8A68V	CS33-8X8
8A70V	CS33-8X10
8C15V	CS37-8X15
8C66V	CS38-8X16
8D15V	CS41-8X15
8D65V	CS44-8X15
8E68V	CS29-8X8
8E70V	CS29-8X10
8E72V	CS29-8X12
8G08V	CS47-8X8
8G12V	CS47-8X12
8G41V	CS50-8X8
8G42V	CS50-8X12
8G71V	CS53-8X8
8G72V	CS53-8X12
8H16V	CS42-8X16
8H66V	CS45-8X16
8J36V	CS34-8X6
8J38V	CS34-8X8

8J42V	CS34-8X12
8K22V	CS39-8X22
8L08V	CS40-8X8
8L66V	CS31-8X6
8L68V	CS31-8X8
8L70V	CS31-8X10
8M15V	CS66-8X15
8M66V	CS67-8X16
8P48V	CS43-8X8
8P56V	CS36-8X6
8P58V	CS36-8X8
8P78V	CS46-8X8
8S66V	CS30-8X6
8S68V	CS30-8X8
8S70V	CS30-8X10
8S72V	CS30-8X12
8T08V	CS21-8X8
8T58V	CS35-8X8
CS01-16X16BR	CS01-16X16BR
1000V	CS01-10X8
1003V	CS01-10X12
1012V	CS08-10X8
1015V	CS08-10X12
1018V	CS08-10X10
1021V	CS09-10X12
1024V	CS09-10X8
1027V	CS09-10X10
1030V	CS11-10X8
1033V	CS11-10X10

1036V	CS11-10X12
1057V	CS25-10X10
1060V	CS26-10X10
1063V	CS25-10X12
1066V	CS26-10X12
1069V	CS27-10X10
1081V	CS10-10X10
10A30V	CS32-10X10
10A32V	CS32-10X12
10A70V	CS33-10X10
10C18V	CS37-10X18
10C70V	CS38-10X20
10D18V	CS41-10X18
10D68V	CS44-10X18
10E70V	CS29-10X10
10E72V	CS29-10X12
10H20V	CS42-10X20
10H70V	CS45-10X20
10J40V	CS34-10X10
10K24V	CS39-10X24
10L70V	CS31-10X10
10L72V	CS31-10X12
10M18V	CS66-10X18
10M70V	CS67-10X20
10P80V	CS46-10X10
10S70V	CS30-10X10
10S72V	CS30-10X12
10T10V	CS21-10X10
1200V	CS01-12X8

1203V	CS01-12X12
1206V	CS05-12X12
1209V	CS04-12X12
12100V	CS28-12X12
1212SV	CS13-12X12
1212V	CS02-12X12
1215V	CS08-12X12
1218V	CS08-12X10
12209V	CS14-12X12
1221V	CS09-12X12
12239V	CS15-12X12
1224V	CS07-12X12
1227V	CS11-12X12
1230V	CS09-12X10
1233V	CS08-12X16
1236V	CS09-12X16
1239V	CS12-12X12
1242V	CS06-12X12
1245V	CS09-12X14
1248V	CS11-12X10
1254V	CS01-12X16
1260V	CS08-12X14
12612V	CS25-12X12
12651V	CS26-12X12
12653V	CS24-12X12
12657V	CS27-12X12
12660V	CS26-12X10
12663V	CS25-12X16
12666V	CS26-12X16



### VARI-CRIMP to CS CROSS REFERENCE

1281V	CS10-12X12
1284V	CS16-12X12
12A30V	CS32-12X10
12A32V	CS32-12X12
12A36V	CS32-12X16
12A72V	CS33-12X12
12C22V	CS37-12X22
12C70V	CS38-12X20
12C75V	CS38-12X25
12D22V	CS41-12X22
12D72V	CS44-12X22
12E72V	CS29-12X12
12G12V	CS47-12X12
12G16V	CS47-12X16
12G42V	CS50-12X12
12G46V	CS50-12X16
12G72V	CS53-12X12
12G76V	CS53-12X16
12J40V	CS34-12X10
12J42V	CS34-12X12
12K30V	CS39-12X30
12L12V	CS40-12X12
12L70V	CS31-12X10
12L72V	CS31-12X12
12L76V	CS31-12X16
12M22V	CS66-12X22
12P52V	CS43-12X12
12P62V	CS36-12X12
12P82V	CS46-12X12

12S70V	CS30-12X10
12S72V	CS30-12X12
12S76V	CS30-12X16
12T12V	CS21-12X12
12T62V	CS35-12X12
1600V	CS01-16X16
1603V	CS01-16X12
1606V	CS05-16X16
1609V	CS04-16X16
16100V	CS28-16X16
1612V	CS08-16X16
1615V	CS08-16X14
16165V	CS13-16X16
1618V	CS09-16X16
16209V	CS14-16X16
1621V	CS09-16X12
16239V	CS15-16X16
1624V	CS09-16X20
1630V	CS11-16X16
1639V	CS12-16X16
16612V	CS25-16X16
16651V	CS26-16X16
16653V	CS24-16X16
16657V	CS27-16X16
1681V	CS10-16X16
16A36V	CS32-16X16
16A40V	CS32-16X20
16A76V	CS33-16X16
16C28V	CS37-16X28

16C80V	CS38-16X30
16E76V	CS29-16X16
16G16V	CS47-16X16
16G20V	CS47-16X20
16G46V	CS50-16X16
16G50V	CS50-16X20
16G76V	CS53-16X16
16G80V	CS53-16X20
16J46V	CS34-16X16
16J50V	CS34-16X20
16K33V	CS39-16X33
16L16V	CS40-16X16
16L76V	CS31-16X16
16L80V	CS31-16X20
16P86V	CS46-16X16
16S72V	CS30-16X12
16S76V	CS30-16X16
16S80V	CS30-16X20
16T16V	CS21-16X16
2000V	CS01-20X20
2005V	CS09-20X20
2008V	CS05-20X20
2015V	CS08-20X20
20677V	CS26-20X20
20697V	CS25-20X20
2081V	CS10-20X20
20A40V	CS32-20X20
20G20V	CS47-20X20
20G50V	CS50-20X20

20G80V	CS53-20X20
20J50V	CS34-20X20
20K36V	CS39-20X36
20L80V	CS31-20X20
20S80V	CS30-20X20