



Visit us online @ [www.AlaskaRubberGroup.com](http://www.AlaskaRubberGroup.com)

## Vacuum Conversion Chart - Water

ATM	PSI	Meter	Feet	MM	Mercury (in.)	Vacuum %
0.3	4.2	3	9' 10 1/8"	220.7	8.7	30
0.4	5.7	4	13' 1 1/2"	294.2	11.6	40
0.5	7.1	5	16' 4 13/16"	367.8	14.5	50
0.6	8.5	6	19' 8 3/16"	441.3	17.4	60
0.7	10.0	7	22' 11 9/16"	514.9	20.3	70
0.8	11.4	8	26' 2 15/16"	588.4	23.2	80
0.9	12.8	9	29' 6 3/8"	662.0	26.0	90
1.0	14.2	10	32' 9 11/16"	735.5	29.0	100